Ref:	NR/L3/ELP/SAI25/Cat-E
Issue:	02
Date:	02 December 2023
Compliance Date:	01 September 2025

NR/L3/ELP/SAI25/Cat-E

Approved Live Working Tasks

Published and Issued by Network Rail, Waterloo General Office, London, SE1 8SW.



This document is the property of Network Rail. It shall not be reproduced in whole or part nor disclosed to a third party without the written permission of Network Rail.

[©] Copyright 2023 Network Rail.

Uncontrolled copy once printed from its electronic source.

Ref:	NR/L3/ELP/SAI25/Cat-E
Issue:	02
Date:	02 December 2023
Compliance Date:	01 September 2025

1 Introduction

This form contains the Electrical Safe System of Work (ESSOW) Category E list of approved tasks for the standard NR/L3/ELP/SAI25/02.

2 Approved Live Working Task

Task	Controls
Removing droppers from ground level where the dropper is foul of the line.	 Conducted where persons remain at least 2.75m from OLE. Only to be completed under Category E – Working on the OLE Live when Route Control has confirmed an Earthed Isolation cannot be achieved. Use of product accepted tools and Live Line insulated poles. Task to be completed in line with Task Risk Control Sheet - NR/L3/MTC/RCS0216/OLE14
Testing of OLE using approved live line indicators	 Conducted where persons remain at least 2.75m from OLE. Conducted by staff with Nominated Person (NP) or Authorised Person (AP) competence. Use of product accepted Live Line Indicator and Live Line insulated poles and/or equipment. Testing only in accordance with: approved section proving document; or, local depot procedure to testing LLIs.
Use of live line pole mounted camera	 Conducted where persons remain at least 2.75m from OLE. Portable cameras shall be used with tested and approved insulated poles Tasks are completed in line with Task Risk Control sheet - NR/L3/MTC/RCS0216/OLE14
Removal of objects/vegetation from ground level from using live line tools.	 Conducted where persons remain at least 2.75m from OLE. Only to be completed under Category E – Working on the OLE Live when Route Control has confirmed an Earthed Isolation cannot be achieved. Work in accordance with Task Risk Control Sheet - RCS0216/OLE04 – Removal of objects/vegetation from Live OLE Work in accordance with Task Risk Control Sheet - RCS0216/OLE04 – Removal of Objects/vegetation from Live OLE Work in accordance with Task Risk Control Sheet - R/L3/MTC/RCS0216/OLE14