Safety Bulletin

A serious incident has taken place



Near miss with advanced lookout near Surbiton

Issued to: All Network Rail line managers,

safety professionals and RISQS

registered contractors

Ref: NRB 16/21

Date of issue: 12/12/2016

Location: Surbiton

Contact: Steven Edwards, Workforce

Health and Safety Advisor



Overview

A three man track patrolling team consisting of a Network Rail COSS/patroller and contract site and advanced lookouts were conducting a track patrol.

The COSS proceeded to inspect the Up Fast line and observe the Up Slow, accompanied by the site lookout. As the COSS and site lookout continued the patrol the advanced lookout walked, as he had been instructed, in the wideway in-between the Up Slow and Up Fast lines.

The advanced lookout, who was approximately 200 yards ahead of the COSS and the site lookout reached the end of the wideway walking path and continued to walk straight ahead into a standard ten foot, which narrowed gradually into a six foot.

At this point the advanced lookout was not in a position of safety and was at risk of being struck by trains approaching on either the Up Fast or Up Slow.

A passenger train approached on the Up Fast and the advanced lookout moved his body toward the Up Slow line as it passed. He could not move into the Up Slow cess because he had observed another train approaching on the Up Slow line.

The trains passed narrowly either side of the advanced lookout, but not at the exact same time.

Discussion Points

While the investigation is underway please discuss the following with your team:

- How do you maintain a safe system of work when using an advanced or distant lookout - especially where a moving worksite is in place?
- How do you ensure that all members of your party have listened, taken in and understood the COSS brief?
- How can you keep checking whether a team mate has mistakenly strayed out of a position of safety, particularly when you are focused on your work?
- What can be done in your areas to make staff aware that they have reached the end of a safe walking route?
- How can we better feed back to our planners whether our Safe System of Work Packs have helped to keep us safe? What else should we feedback to them?

Copies of Safety Bulletins are available on Safety Central